

---

## **Pilgrim Inspections**

Informations générales

### **SIRET**

74998713700033

### **Responsable(s)**

Président : Anne-Marie HAUTE

Directeur Technique : Frédéric CHESNIN

### **Adresse**

38 rue Jean Monnet

---

---

44450

La Chapelle Basse Mer

France

## **Tél**

0240698541

<http://www.pilgrim-consultant.com>

contact@pilgrim-consultant.com

Présentation

## **Activité détaillée**

Spécialisés dans l'inspection, nous avons développé des drones permettant une inspection visuelle détaillée.

Nos drones de grande capacité embarquent 2 caméra Full HD ainsi qu'une caméra thermique, à partir de ces enregistrements de données, nous reconstruisons les pales en 3D avec la granulométrie afin de pouvoir qualifier et mesurer les impacts, fissures et autres anomalies de surface.

Specialized and experienced in inspection, we developed drones (UAV) enable to perform accurate inspection at height

Our drones with heavy pay load are equipped with 2 HD cameras and a thermal camera also. From the collection of the data we can modelize in 3 D the blades with accurate aspect in order to define any cracks or any other damage on the blade surface.

